



508817

Former Statler Hilton Hotel Site  
TDD # 0308-003  
Site Photo Log

PHOTO ID	DATE	DIRECTION	DESCRIPTION	PHOTO TAKEN BY
FSHH-100	9/22/2003	N	ERRS pumping water from sub-basement	L. Ash
FSHH-101	9/22/2003	NW	10,000 gallon tanker truck on-site removing water from sub-basement	L. Ash
FSHH-102	9/22/2003	S	Pumping water into 7,000 gallon tanker truck	L. Ash
FSHH-103	9/22/2003	N	10,000 gallon tanker truck leaving site for USL for disposal	L. Ash
FSHH-104	9/22/2003	SW	Pumping of water from sub-basement	L. Ash
FSHH-105	9/22/2003	E	ERRS scraping beams in basement area	L. Ash
FSHH-106	9/22/2003	W	Drums of oil and water from transformer area ready for disposal	L. Ash
FSHH-107	9/22/2003	N	Pump removing water from sub-basement	L. Ash
FSHH-108	9/22/2003	NW	7,000 gallon tanker checking water level	L. Ash
FSHH-109	9/23/2003	N	7,000 gallon tanker leaving site to USL for disposal	L. Ash
FSHH-110	9/23/2003	W	Footprints of those who broke into site	L. Ash
FSHH-111	9/23/2003	N	Truck leaving site with full roll-off	L. Ash
FSHH-112	9/23/2003	N	Empty roll-off delivered to site	L. Ash
FSHH-113	9/23/2003	W	Fire extinguisher dust from break in	L. Ash
FSHH-114	9/23/2003	SE	Capicator closet where capicators once were	L. Ash
FSHH-115	9/23/2003	E	ERRS scraping sump area	L. Ash
FSHH-116	9/23/2003	E	ERRS scraping and removing loose debris	L. Ash
FSHH-117	9/23/2003	W	Suspect ACM found in basement area	L. Ash
FSHH-118	9/23/2003	E	Debris pile ready for removal into roll-off	L. Ash
FSHH-119	9/23/2003	N	Debris pile ready for removal into roll-off	L. Ash
FSHH-120	9/23/2003	E	ERRS scraping and removing loose debris	L. Ash
FSHH-121	9/23/2003	SE	Fire extinguisher dust from break in	L. Ash
FSHH-122	9/23/2003	NW	7,000 gallon truck leaving site to USL for disposal	L. Ash
FSHH-123	9/23/2003	E	Pump with damaged elbow	L. Ash
FSHH-124	9/23/2003	E	PVC pipe damaged	L. Ash
FSHH-125	9/23/2003	W	Use of the discharge flat hose instead of the PVC	L. Ash
FSHH-126	9/24/2003	E	Pump with asbestos bags caught	L. Ash
FSHH-127	9/24/2003	N	Pump with asbestos bags caught	L. Ash
FSHH-128	9/24/2003	E	ERRS removing bags from pump	L. Ash
FSHH-129	9/24/2003	S	ERRS attaching grate on bottom to prevent debris from being pulled into pump	L. Ash
FSHH-130	9/24/2003	E	Pump after removing estimated 250,000 gallons from sub-basement	L. Ash
FSHH-131	9/24/2003	E	ERRS grabbing concrete core sample from transformer area.	L. Ash
FSHH-132	9/25/2003	E	Box being loaded into sub-basement for debris removal	L. Ash
FSHH-133	9/25/2003	W	Debris being loaded into roll-off box for disposal	L. Ash
FSHH-134	9/25/2003	E	ERRS using mini-loader to remove debris in sub-basement	L. Ash
FSHH-135	9/25/2003	S	Moving pump into sump area with mini-loader to allow better intake	L. Ash
FSHH-136	9/25/2003	S	Moving pump into sump area with mini-loader to allow better intake	L. Ash
FSHH-137	9/25/2003	E	Moving pump into sump area with mini-loader to allow better intake	L. Ash
FSHH-138	9/25/2003	W	ERRS changing out pump for better intake	L. Ash
FSHH-139	9/26/2003	E	Crew removing debris from basement	L. Ash
FSHH-140	9/29/2003	SW	Loading of debris from basement	L. Ash
FSHH-141	9/29/2003	E	Power washing walls and ceilings in subbasement	L. Ash
FSHH-142	9/29/2003	E	Power washing walls and ceilings in subbasement	L. Ash
FSHH-144	9/29/2003	W	Sub-basement where small pump set into sump to pump water to elevator area	L. Ash
FSHH-145	9/30/2003	SE	Empty roll-off delivered to site	L. Ash
FSHH-146	9/30/2003	SW	Crew unloading hose for vac truck	L. Ash
FSHH-147	9/30/2003	E	Hose for vac truck being loaded down into sub-basement	L. Ash
FSHH-148	9/30/2003	SW	Vac truck on site removing water from sub-basement	L. Ash
FSHH-149	9/30/2003	S	Connection of hose from Vac truck into tanker truck	L. Ash
FSHH-150	9/30/2003	NW	Water pumping from Vac truck into tanker for disposal to USL	L. Ash
FSHH-151	9/30/2003	E	4" and 6" pumps, 4" pump removing water from sub-basement	L. Ash
FSHH-152	9/30/2003	E	Power washing of walls and ceiling in subbasement	L. Ash
FSHH-153	9/30/2003	E	Power washing of walls and ceiling in subbasement	L. Ash
FSHH-154	9/30/2003	NE	Large sump found in subbasement, vac truck removing water	L. Ash
FSHH-155	9/30/2003	E	Small sump in subbasement with pipe draining water into it	L. Ash
FSHH-156	10/2/2003	S	Crew loading mini excavator with jack hammer extension down into basement	L. Ash
FSHH-157	10/2/2003	E	Mini excavator dropped down to basement	L. Ash
FSHH-158	10/2/2003	SW	Concrete corer in sub-basement	L. Ash
FSHH-159	10/2/2003	NE	Crew deconing drill bit	L. Ash
FSHH-160	10/2/2003	SW	Core in backroom of basement	L. Ash
FSHH-161	10/2/2003	SW	Coring of sub-basement, pressure water keeping dust down	L. Ash
FSHH-162	10/2/2003	SW	Coring of sub-basement	L. Ash
FSHH-163	10/2/2003	SW	Coring of sub-basement	L. Ash
FSHH-164	10/2/2003	E	Mini excavator with jack hammer breaking concrete in main transformer area	L. Ash
FSHH-165	10/2/2003	E	Jack hammer breaking concrete	L. Ash
FSHH-166	10/2/2003	E	Jack hammer breaking concrete	L. Ash
FSHH-167	10/3/2003	E	Crew pulling mini-loader out of sub-basement	L. Ash
FSHH-168	10/3/2003	NE	Mini-loader from sub-basement moved up to basement	L. Ash
FSHH-169	10/6/2003	NE	Large sump found in subbasement, filled completely with water	L. Ash
FSHH-170	10/6/2003	NW	Sucking of water from sub-basement with Vac truck	L. Ash
FSHH-171	10/6/2003	S	Small storage room in sub-basement filled with bricks	L. Ash
FSHH-172	10/6/2003	NW	Errs checking tanker truck for heel	L. Ash
FSHH-173	10/7/2003	E	Jack hammer breaking concrete in basement main transformer area	L. Ash
FSHH-174	10/7/2003	S	Vac truck sucking water from sumps in basement in main transformer area	L. Ash
FSHH-175	10/7/2003	NW	Power washing walls and ceilings in subbasement	L. Ash
FSHH-176	10/7/2003	NW	Power washing walls and ceilings in subbasement	L. Ash
FSHH-177	10/7/2003	SE	Power washing walls and ceilings in subbasement	L. Ash
FSHH-178	10/7/2003	SE	Crew cleaning out Vac truck, drumming debris	L. Ash

## Former Statler Hilton Hotel Site

TDD # 0308-003

## Site Photo Log

FSHH-179	10/7/2003	S	55 gallon drum of excess waste in Vac truck	L. Ash
FSHH-180	10/7/2003	E	Crew cleaning out Vac truck, drumming debris	L. Ash
FSHH-181	10/7/2003	S	Waste from Vac truck being drummed	L. Ash
FSHH-182	10/7/2003	SE	Vac truck with door open to get access to remaining debris	L. Ash
FSHH-183	10/7/2003	S	Layer of debris and excess waste in vac truck that was drummed	L. Ash
FSHH-184	10/8/2003	E	Mini excavator with bucket attachment removing slag and concrete from main transformer area	L. Ash
FSHH-185	10/8/2003	E	ERRS busting and removing concrete from main transformer area	L. Ash
FSHH-186	10/8/2003	SE	Capicator being removed from basement and placed into roll-off	L. Ash
FSHH-187	10/9/2003	SW	Busted up concrete and tile in main transformer area	L. Ash
FSHH-188	10/9/2003	E	Busted up concrete and tile in main transformer area	L. Ash
FSHH-189	10/9/2003	E	Busted up concrete and tile in main transformer area	L. Ash
FSHH-190	10/9/2003	SW	Busted up concrete and tile in main transformer area	L. Ash
FSHH-191	10/9/2003	SE	Floor in sump room after power washing	L. Ash
FSHH-192	10/9/2003	SE	Floor in sump room after power washing	L. Ash
FSHH-193	10/9/2003	SW	Floor in sump room after power washing	L. Ash
FSHH-194	10/9/2003	SW	Floor in sump room after power washing	L. Ash
FSHH-195	10/9/2003	SW	ERRS power washing in sub-basement	L. Ash
FSHH-196	10/9/2003	SW	ERRS power washing in sub-basement	L. Ash
FSHH-197	10/9/2003	SW	ERRS power washing in sub-basement	L. Ash
FSHH-198	10/9/2003	SW	ERRS power washing in sub-basement	L. Ash
FSHH-199	10/9/2003	SW	ERRS collecting concrete core sample	L. Ash
FSHH-200	10/9/2003	SW	ERRS collecting concrete core sample	L. Ash
FSHH-201	10/13/2003	W	Broken arm on mini-loader	L. Ash
FSHH-202	10/13/2003	N	Concrete core sampling in sub-basement	L. Ash
FSHH-203	10/14/2003	E	ERRS breaking concrete in main transformer area	L. Ash
FSHH-204	10/14/2003	NE	Demolished wall in main transformer area	L. Ash
FSHH-205	10/14/2003	NW	ERRS deconing drill bit for concrete core sampler	L. Ash
FSHH-206	10/14/2003	SW	Small room in basement by elevator shaft with bricks	L. Ash
FSHH-207	10/14/2003	S	ERRS cutting capicator closet for removal	L. Ash
FSHH-208	10/14/2003	E	Pieces of capicator closet being cut for disposal into roll-off	L. Ash
FSHH-209	10/14/2003	N	ERRS removing capicator closet	L. Ash
FSHH-210	10/14/2003	S	Large room by back spill area is basement. No visual staining and no flooding occurred	L. Ash
FSHH-211	10/14/2003	E	Nitric Acid found in basement	L. Ash
FSHH-212	10/14/2003	N	ERRS removing capicator closet	L. Ash
FSHH-213	10/16/2003	NW	Staged debris for removal	L. Ash
FSHH-214	10/16/2003	E	Main transformer area with concrete busted out	L. Ash
FSHH-215	10/16/2003	SE	Removal of busted out concrete	L. Ash
FSHH-216	10/16/2003	SW	Suction hose found inside of Vac truck after removal of water in sub-basement	L. Ash
FSHH-217	10/16/2003	SW	Suction hose found inside of Vac truck after removal of water in sub-basement	L. Ash
FSHH-218	10/17/2003	E	Crew cleaning up debris from fallen wall in basement by elevator shaft	L. Ash
FSHH-219	10/17/2003	NE	Crew cleaning up debris from fallen wall in basement by elevator shaft	L. Ash
FSHH-220	10/17/2003	SE	ERRS vacuuming up debris in main transformer area	L. Ash
FSHH-221	10/17/2003	E	Main transformer area ready for power washing	L. Ash
FSHH-222	10/17/2003	SW	ERRS removing debris and dust from basement floor	L. Ash
FSHH-223	10/17/2003	E	Back room spill area with concrete busted out	L. Ash
FSHH-224	10/18/2003	E	Area where wall fell, all debris removed	L. Ash
FSHH-225	10/18/2003	NW	Debris pile ready for removal into roll-off	L. Ash
FSHH-226	10/22/2003	SE	East side of elevator shaft, ERRS scraping top layer off for disposal and resample	L. Ash
FSHH-227	10/22/2003	SW	Sample FSHH-SOLID-008	L. Ash
FSHH-228	10/22/2003	SW	Sample FSHH-SOLID-008	L. Ash
FSHH-229	10/23/2003	SW	Crew scraping top layer of elevator shaft	R.Nemirovsky
FSHH-230	10/23/2003	SE	Crew scraping down table in basement.	R.Nemirovsky
FSHH-231	10/24/2003	NW	Crew removing debris from trenches in basement laundry room.	R.Nemirovsky
FSHH-232	10/24/2003	SW	Crew pulling in loading bucket on crane cable through elevator shaft.	R.Nemirovsky
FSHH-233	10/25/2003	NE	View of area of basement missing lower 2ft of wall.	J. Kimble
FSHH-234	10/25/2003	W	View of concrete busting progress in small transformer room.	J. Kimble
FSHH-235	10/27/2003	SE	Crew pressure washing in main transformer area.	R.Nemirovsky
FSHH-236	10/27/2003	E	Crew pressure washing in laundry room in basement.	R.Nemirovsky
FSHH-237	10/27/2003	E	Crew pressure washing in rooms east of laundry room.	R.Nemirovsky
FSHH-238	10/28/2003	SW	Concrete core sampling in basement	L. Ash
FSHH-239	10/28/2003	S	Concrete core sampling in basement	L. Ash
FSHH-240	10/30/2003	E	Crew pressure washing in machinery room	L. Ash
FSHH-241	10/30/2003	SE	Crew sucking up water in machinery room	L. Ash
FSHH-242	10/30/2003	SW	Crew drumming wash water from machinery room pressure washing.	L. Ash
FSHH-243	10/30/2003	N	Crew storing rinse water in trenches for removal	L. Ash
FSHH-244	11/4/2003	SE	Trench in main transformer area, wash water staged in trench for future removal	L. Ash
FSHH-245	11/4/2003	SE	Trench in main transformer area, wash water staged in trench for future removal	L. Ash
FSHH-246	11/4/2003	SE	Plugging drain with concrete in trench where waste water staged	L. Ash
FSHH-247	11/4/2003	SE	Plugging drain in trench where waste water staged	L. Ash
FSHH-248	11/4/2003	SE	Plugging drain in trench where waste water staged	L. Ash
FSHH-249	11/5/2003	E	Pressure washing trenches in laundry room	L. Ash
FSHH-250	11/5/2003	W	Debris pile ready for removal into roll-off	L. Ash
FSHH-251	11/5/2003	E	Equipment staging area in basement	L. Ash
FSHH-252	11/5/2003	S	Pressure washing basement areas	L. Ash
FSHH-253	11/5/2003	E	Pressure washing laundry room in basement	L. Ash
FSHH-254	11/6/2003	SE	Areas that were > 50 ppm and require concrete to be busted out further	L. Ash
FSHH-255	11/6/2003	W	Debris pile staged in basement, ready for disposal into on-site roll-off	L. Ash
FSHH-256	11/6/2003	SE	Loading busted concrete from hot area into loader for disposal	L. Ash
FSHH-257	11/6/2003	NE	Busting up concrete in area where sample > 50ppm	L. Ash
FSHH-258	11/6/2003	SE	Loading busted concrete from hot area into loader for disposal	L. Ash

## Former Statler Hilton Hotel Site

TDD # 0308-003

Site Photo Log

FSHH-259	11/7/2003	NW	Debris from basement being loaded out into onsite roll-off box	L. Ash
FSHH-260	11/7/2003	NW	Water tanks supplying water into basement for pressure washer	L. Ash
FSHH-261	11/7/2003	NE	Pressure washing laundry room in basement	L. Ash
FSHH-262	11/7/2003	NE	Pressure washing laundry room in basement	L. Ash
FSHH-263	11/7/2003	SW	Pressure washing hallway in basement	L. Ash
FSHH-264	11/7/2003	SE	ERRS removing ACM located inside machinery	L. Ash
FSHH-265	11/7/2003	SW	Loading of debris into box for disposal into roll-off	L. Ash
FSHH-266	11/7/2003	SE	Vac truck in roll-off for disposal	L. Ash
FSHH-267	11/10/2003	SE	Drums of oil and water from transformer area ready for disposal	L. Ash
FSHH-268	11/11/2003	N	Elevator shaft being sucked out with vac truck	L. Ash
FSHH-269	11/12/2003	S	Sump in main transformer area being pressure washed and sucked out	L. Ash
FSHH-270	11/12/2003	SE	Sump in main transformer area after pressure washing	L. Ash
FSHH-271	11/12/2003	S	Sump in main transformer area after pressure washing	L. Ash
FSHH-272	11/12/2003	SE	Trench in main transformer area, water leaking in from east corner	L. Ash
FSHH-273	11/12/2003	S	Sump in main transformer area being sucked out	L. Ash
FSHH-274	11/12/2003	S	Sump in main transformer area being pressure washed and sucked out	L. Ash
FSHH-275	11/12/2003	E	Sample location FSHH-CC-124, area busted up another 4"	L. Ash
FSHH-276	11/12/2003	E	Busting up concrete in area where sample FSHH-CCC-004 was collected	L. Ash
FSHH-277	11/14/2003	W	Area where debris was staged in basement	L. Ash
FSHH-278	11/14/2003	NE	Concrete core sampling in basement	L. Ash
FSHH-279	11/17/2003	SE	Shop Vac's being disposed of into on-site roll-off	L. Ash
FSHH-280	11/17/2003	SE	Shop Vac's being disposed of into on-site roll-off	L. Ash
FSHH-281	11/17/2003	SE	Shop Vac's being disposed of into on-site roll-off	L. Ash

## Former Statler Hilton Hotel Site

TDD # 0308-003

Site Photo Log

PHOTO ID	DATE	DIRECTION	DESCRIPTION	PHOTO TAKEN BY
FSHH-100	9/22/2003	N	ERRS pumping water from sub-basement	L. Ash
FSHH-101	9/22/2003	NW	10,000 gallon tanker truck on-site removing water from sub-basement	L. Ash
FSHH-102	9/22/2003	S	Pumping water into 7,000 gallon tanker truck	L. Ash
FSHH-103	9/22/2003	N	10,000 gallon tanker truck leaving site for USL for disposal	L. Ash
FSHH-104	9/22/2003	SW	Pumping of water from sub-basement	L. Ash
FSHH-105	9/22/2003	E	ERRS scraping beams in basement area	L. Ash
FSHH-106	9/22/2003	W	Drums of oil and water from transformer area ready for disposal	L. Ash
FSHH-107	9/22/2003	N	Pump removing water from sub-basement	L. Ash
FSHH-108	9/22/2003	NW	7,000 gallon tanker checking water level	L. Ash
FSHH-109	9/23/2003	N	7,000 gallon tanker leaving site to USL for disposal	L. Ash
FSHH-110	9/23/2003	W	Footprints of those who broke into site	L. Ash
FSHH-111	9/23/2003	N	Truck leaving site with full roll-off	L. Ash
FSHH-112	9/23/2003	N	Empty roll-off delivered to site	L. Ash
FSHH-113	9/23/2003	W	Fire extinguisher dust from break in	L. Ash
FSHH-114	9/23/2003	SE	Capicator closet where capicators once were	L. Ash
FSHH-115	9/23/2003	E	ERRS scraping sump area	L. Ash
FSHH-116	9/23/2003	E	ERRS scraping and removing loose debris	L. Ash
FSHH-117	9/23/2003	W	Suspect ACM found in basement area	L. Ash
FSHH-118	9/23/2003	E	Debris pile ready for removal into roll-off	L. Ash
FSHH-119	9/23/2003	N	Debris pile ready for removal into roll-off	L. Ash
FSHH-120	9/23/2003	E	ERRS scraping and removing loose debris	L. Ash
FSHH-121	9/23/2003	SE	Fire extinguisher dust from break in	L. Ash
FSHH-122	9/23/2003	NW	7,000 gallon truck leaving site to USL for disposal	L. Ash
FSHH-123	9/23/2003	E	Pump with damaged elbow	L. Ash
FSHH-124	9/23/2003	E	PVC pipe damaged	L. Ash
FSHH-125	9/23/2003	W	Use of the discharge flat hose instead of the PVC	L. Ash
FSHH-126	9/24/2003	E	Pump with asbestos bags caught	L. Ash
FSHH-127	9/24/2003	N	Pump with asbestos bags caught	L. Ash
FSHH-128	9/24/2003	E	ERRS removing bags from pump	L. Ash
FSHH-129	9/24/2003	S	ERRS attaching grate on bottom to prevent debris from being pulled into pump	L. Ash
FSHH-130	9/24/2003	E	Pump after removing estimated 250,000 gallons from sub-basement	L. Ash
FSHH-131	9/24/2003	E	ERRS grabbing concrete core sample from transformer area.	L. Ash
FSHH-132	9/25/2003	E	Box being loaded into sub-basement for debris removal	L. Ash
FSHH-133	9/25/2003	W	Debris being loaded into roll-off box for disposal	L. Ash
FSHH-134	9/25/2003	E	ERRS using mini-loader to remove debris in sub-basement	L. Ash
FSHH-135	9/25/2003	S	Moving pump into sump area with mini-loader to allow better intake	L. Ash
FSHH-136	9/25/2003	S	Moving pump into sump area with mini-loader to allow better intake	L. Ash
FSHH-137	9/25/2003	E	Moving pump into sump area with mini-loader to allow better intake	L. Ash
FSHH-138	9/25/2003	W	ERRS changing out pump for better intake	L. Ash
FSHH-139	9/26/2003	E	Crew removing debris from basement	L. Ash
FSHH-140	9/29/2003	SW	Loading of debris from basement	L. Ash
FSHH-141	9/29/2003	E	Power washing walls and ceilings in subbasement	L. Ash
FSHH-142	9/29/2003	E	Power washing walls and ceilings in subbasement	L. Ash
FSHH-144	9/29/2003	W	Sub-basement where small pump set into sump to pump water to elevator area	L. Ash
FSHH-145	9/30/2003	SE	Empty roll-off delivered to site	L. Ash
FSHH-146	9/30/2003	SW	Crew unloading hose for vac truck	L. Ash
FSHH-147	9/30/2003	E	Hose for vac truck being loaded down into sub-basement	L. Ash
FSHH-148	9/30/2003	SW	Vac truck on site removing water from sub-basement	L. Ash
FSHH-149	9/30/2003	S	Connection of hose from Vac truck into tanker truck	L. Ash
FSHH-150	9/30/2003	NW	Water pumping from Vac truck into tanker for disposal to USL	L. Ash
FSHH-151	9/30/2003	E	4" and 6" pumps, 4" pump removing water from sub-basement	L. Ash
FSHH-152	9/30/2003	E	Power washing of walls and ceiling in subbasement	L. Ash
FSHH-153	9/30/2003	E	Power washing of walls and ceiling in subbasement	L. Ash
FSHH-154	9/30/2003	NE	Large sump found in subbasement, vac truck removing water	L. Ash
FSHH-155	9/30/2003	E	Small sump in subbasement with pipe draining water into it	L. Ash
FSHH-156	10/2/2003	S	Crew loading mini excavator with jack hammer extension down into basement	L. Ash
FSHH-157	10/2/2003	E	Mini excavator dropped down to basement	L. Ash
FSHH-158	10/2/2003	SW	Concrete corer in sub-basement	L. Ash
FSHH-159	10/2/2003	NE	Crew deconing drill bit	L. Ash
FSHH-160	10/2/2003	SW	Core in backroom of basement	L. Ash
FSHH-161	10/2/2003	SW	Coring of sub-basement, pressure water keeping dust down	L. Ash
FSHH-162	10/2/2003	SW	Coring of sub-basement	L. Ash
FSHH-163	10/2/2003	SW	Coring of sub-basement	L. Ash
FSHH-164	10/2/2003	E	Mini excavator with jack hammer breaking concrete in main transformer area	L. Ash
FSHH-165	10/2/2003	E	Jack hammer breaking concrete	L. Ash
FSHH-166	10/2/2003	E	Jack hammer breaking concrete	L. Ash
FSHH-167	10/3/2003	E	Crew pulling mini-loader out of sub-basement	L. Ash
FSHH-168	10/3/2003	NE	Mini-loader from sub-basement moved up to basement	L. Ash
FSHH-169	10/6/2003	NE	Large sump found in subbasement, filled completely with water	L. Ash
FSHH-170	10/6/2003	NW	Sucking of water from sub-basement with Vac truck	L. Ash
FSHH-171	10/6/2003	S	Small storage room in sub-basement filled with bricks	L. Ash
FSHH-172	10/6/2003	NW	Errs checking tanker truck for heel	L. Ash
FSHH-173	10/7/2003	E	Jack hammer breaking concrete in basement main transformer area	L. Ash
FSHH-174	10/7/2003	S	Vac truck sucking water from sumps in basement in main transformer area	L. Ash
FSHH-175	10/7/2003	NW	Power washing walls and ceilings in subbasement	L. Ash
FSHH-176	10/7/2003	NW	Power washing walls and ceilings in subbasement	L. Ash
FSHH-177	10/7/2003	SE	Power washing walls and ceilings in subbasement	L. Ash
FSHH-178	10/7/2003	SE	Crew cleaning out Vac truck, drumming debris	L. Ash

## Former Statler Hilton Hotel Site

TDD # 0308-003

Site Photo Log

FSHH-179	10/7/2003	S	55 gallon drum of excess waste in Vac truck	L. Ash
FSHH-180	10/7/2003	E	Crew cleaning out Vac truck, drumming debris	L. Ash
FSHH-181	10/7/2003	S	Waste from Vac truck being drummed	L. Ash
FSHH-182	10/7/2003	SE	Vac truck with door open to get access to remaining debris	L. Ash
FSHH-183	10/7/2003	S	Layer of debris and excess waste in vac truck that was drummed	L. Ash
FSHH-184	10/8/2003	E	Mini excavator with bucket attachment removing slag and concrete from main transformer area	L. Ash
FSHH-185	10/8/2003	E	ERRS busting and removing concrete from main transformer area	L. Ash
FSHH-186	10/8/2003	SE	Capicator being removed from basement and placed into roll-off	L. Ash
FSHH-187	10/9/2003	SW	Busted up concrete and tile in main transformer area	L. Ash
FSHH-188	10/9/2003	E	Busted up concrete and tile in main transformer area	L. Ash
FSHH-189	10/9/2003	E	Busted up concrete and tile in main transformer area	L. Ash
FSHH-190	10/9/2003	SW	Busted up concrete and tile in main transformer area	L. Ash
FSHH-191	10/9/2003	SE	Floor in sump room after power washing	L. Ash
FSHH-192	10/9/2003	SE	Floor in sump room after power washing	L. Ash
FSHH-193	10/9/2003	SW	Floor in sump room after power washing	L. Ash
FSHH-194	10/9/2003	SW	Floor in sump room after power washing	L. Ash
FSHH-195	10/9/2003	SW	ERRS power washing in sub-basement	L. Ash
FSHH-196	10/9/2003	SW	ERRS power washing in sub-basement	L. Ash
FSHH-197	10/9/2003	SW	ERRS power washing in sub-basement	L. Ash
FSHH-198	10/9/2003	SW	ERRS power washing in sub-basement	L. Ash
FSHH-199	10/9/2003	SW	ERRS collecting concrete core sample	L. Ash
FSHH-200	10/9/2003	SW	ERRS collecting concrete core sample	L. Ash
FSHH-201	10/13/2003	W	Broken arm on mini-loader	L. Ash
FSHH-202	10/13/2003	N	Concrete core sampling in sub-basement	L. Ash
FSHH-203	10/14/2003	E	ERRS breaking concrete in main transformer area	L. Ash
FSHH-204	10/14/2003	NE	Demolished wall in main transformer area	L. Ash
FSHH-205	10/14/2003	NW	ERRS deconing drill bit for concrete core sampler	L. Ash
FSHH-206	10/14/2003	SW	Small room in basement by elevator shaft with bricks	L. Ash
FSHH-207	10/14/2003	S	ERRS cutting capicator closet for removal	L. Ash
FSHH-208	10/14/2003	E	Pieces of capicator closet being cut for disposal into roll-off	L. Ash
FSHH-209	10/14/2003	N	ERRS removing capicator closet	L. Ash
FSHH-210	10/14/2003	S	Large room by back spill area is basement. No visual staining and no flooding occurred	L. Ash
FSHH-211	10/14/2003	E	Nitric Acid found in basement	L. Ash
FSHH-212	10/14/2003	N	ERRS removing capicator closet	L. Ash
FSHH-213	10/16/2003	NW	Staged debris for removal	L. Ash
FSHH-214	10/16/2003	E	Main transformer area with concrete busted out	L. Ash
FSHH-215	10/16/2003	SE	Removal of busted out concrete	L. Ash
FSHH-216	10/16/2003	SW	Suction hose found inside of Vac truck after removal of water in sub-basement	L. Ash
FSHH-217	10/16/2003	SW	Suction hose found inside of Vac truck after removal of water in sub-basement	L. Ash
FSHH-218	10/17/2003	E	Crew cleaning up debris from fallen wall in basement by elevator shaft	L. Ash
FSHH-219	10/17/2003	NE	Crew cleaning up debris from fallen wall in basement by elevator shaft	L. Ash
FSHH-220	10/17/2003	SE	ERRS vacuuming up debris in main transformer area	L. Ash
FSHH-221	10/17/2003	E	Main transformer area ready for power washing	L. Ash
FSHH-222	10/17/2003	SW	ERRS removing debris and dust from basement floor	L. Ash
FSHH-223	10/17/2003	E	Back room spill area with concrete busted out	L. Ash
FSHH-224	10/18/2003	E	Area where wall fell, all debris removed	L. Ash
FSHH-225	10/18/2003	NW	Debris pile ready for removal into roll-off	L. Ash